



About the firmware version 2.72 update

Last Modified: April 17th, 2023

What's included in 2.72 (changes since 2.70)?

Fixes and improvements:

- Fixed inconsistency in web interface when fast switching was enabled
- Fixed ring state change trap issue

Notes:

- Recommended version for most users
- Since SPDM version 2.70 multiple Branch and Total registers are moved to a higher register-range 21000-24054. This means that all PDUs on the data bus must have the same firmware version as the bridge PDU to stay compatible. If a bridge PDU is version 2.70 or newer, versions lower than 2.70 are not supported on the data bus, this works also the other way around.

Installing this firmware

Installation of firmware is preferred by using the Schleifenbauer Product Service Tool (SPST version 1.4.5). There is a specific *SPST user manual* available on the Schleifenbauer website.

Notes:

- While updating or restarting the devices, power distribution will not be interrupted.