

About the firmware version 2.66 update

Last Modified: September 1st, 2021

What's included in 2.66 (changes since 2.64)?

New features:

- Neutral current measurement (on three phase PDUs built from summer '21, s/n starting with 'SP')
- Residual current alert added

Fixes and improvements:

- General performance and stability improvements

Notes:

- Updated MIB files

Installing this firmware

Installation of firmware is preferred by using the Schleifenbauer Product Service Tool (SPST version 1.2.0). There is a specific *SPST user manual* available on the Schleifenbauer website.

Notes:

- While updating or restarting the devices, power distribution will not be interrupted.