

About the firmware version 2.06 update

Last Modified: February 25th, 2015

Summary

This release of the hPDU firmware fixes some issues, and is advised for all users of the hybrid range of PDUs.

Important warning!

Make sure you update to 2.06 before updating to 2.10. The hPDU firmware might get locked at version 2.02 when updating from 2.02 to 2.10 directly! The supplied firmware updater tools will prevent this.

What's included in 2.06 (changes since 2.02)?

- Preparation of the hPDU's internal memory for receiving larger updates (like 2.10). This happens without affecting normal hPDU operation, and no data will be lost during the preparation.
- SPDm version 1.26
- Added support for hPDU's on-board dry switch input
- New pages on LCD display showing Ethernet link status, interface status and hPDU mode (note: mode is still fixed to 'classic' as in 2.02)

Installing this firmware

Versions 2.02 and 2.06 can only receive firmware updates over the classic data bus (by using a Gateway or RS485 converter together with the supplied updater tools). From version 2.10, the hPDU can receive firmware updates over the IP API as well.

Use the supplied firmware updater tool by following the instructions in the *Firmware updater tool manual*. Note: uploading 2.xx bin files in the Gateway's web interface is not possible!

Note: the outlets will not be powered down during update or rebooting of the PDUs!