



**SCHLEIFENBAUER**

LIVING FOR THE POWER TO DELIVER

## About the firmware version 2.62 update

Last Modified: October 9th, 2020

### What's included in 2.62 (changes since 2.60)?

#### New features:

- Added choice of dhcp hostname: serial number or sysname
- Added locate function that blinks display at request
- Added devicetype readout (sdbDevIdDeviceType)

#### Fixes and improvements:

- Improved firmware update handling
- Improved usb detection and device handling
- Fixes extraneous sensor change alerts
- Miscellaneous minor improvements and fixes
- Fixed SNMP V3 encryption issues
- Fixed SNMP-trap temperature alert (specific-trap)
- Updated German language items
- Fixed deactivating usernames
- Fixed ip ranges for blocking access
- Fixed unit address field length
- Optimization of TLS/HTTPS and fixed related issues
- General performance and stability improvements

#### Notes:

- Updated MIB files

### Installing this firmware

Installation of firmware is preferred by using the Schleifenbauer Product Service Tool (SPST version 1.1.8). There is a specific *SPST user manual* available on the Schleifenbauer website.

#### Notes:

- Uploading 2.xx bin files in the Gateway's web interface is not possible!
- While updating or restarting the devices, power distribution will not be interrupted.