



## About the SPST version 1.4.0 update

Last Modified: April, 8th, 2022

### Minimum requirements:

Windows OS	Mac OS	Linux OS
Windows 7 or higher	10.15 or higher	Ubuntu 18 or higher

### What's included in 1.4.0 (changes since 1.3.0)?

This version of SPST contains PDU firmware version 0266 as well as an updated SPDM and some minor bug fixes. In addition it has some fixes related to importing PDU data from files and some UI improvements.

#### New features:

- The latest firmware, 0266, for Schleifenbauer PDUs has been added to SPST.
- A prompt is added that asks the user to reboot when registers are updated that require a reboot to become in effect.
- Multiplatform locking and a user prompt that can deal with a lockfile still being in use.
- The SPDM has been updated to reflect the current firmware.

#### Fixes and improvements:

- A bug in the IPAPI group read could skip registers if the group was not sequential in SPDM.
- Fix a crash when importing data from XLSX files.
- UI improvements.